Annexure D

BUILDING SAFETY CERTIFICATE

No. **Date: 04.09.2024**

It is Certified that existing building **Maharishi Vidya Mandir Senior Secondary** School Machewa Mahasamund (name of the building or Premises at **Village – Machewa, Post – Bamhani Mahasamund** (Address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground Floor First Floor Second Floor	Ground Floor First Floor Second Floor				

The building is owned/occupied by **Maharishi Vidya Mandir Senior Secondary School** (name of the institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **P.W.D (B/R) Division Mahasamund** (Name of Department / Govt.) on **03.09.2024** (Date of inspection) in the presence of **Shree Rajesh Kumar Tiwari** (Name and addresses of the Manage/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **03.09.2024** For a period of **02.09.2026** Years in accordance with rule and subject to compliance of the specific conditions as appended.

1.

2.

3.

4.

Issued on **04.09.2024** at **Mahasamund** by

Strike out whichever is not applicable in case of block is more than six use separate sheet for detail.

Signature with Seal: .....Sub Divisional Officer
P.W.D.(B/R) Sub-Dn.No.1
Name: .....Mahasamund (C.G.)

Designation: .....

Name & Address of Department/Office: .....

.....